

Urgent Field Safety Notice

For attention of: **Healthcare Professionals (HCP)**

Manufacturer's reference: SB_RDC_2023_02/03/04

SRN number: DE-MF-000006276

Location, Date

Important information related to the Accu-Chek Solo system:

- 1) Replacement of Accu-Chek Solo diabetes manager
- 2) Updated Accu-Chek Solo handling instructions

Dear Healthcare Professional [please personalise],

A few weeks ago, we notified you about a software issue related to the bolus data screen of the Accu-Chek Solo diabetes manager. We are happy to let you know today that the issue has been resolved and you can advise your patients using the Accu-Chek Solo system to contact us at their earliest convenience via our Roche Diabetes Care Customer Care line at xxx-xxx-xxx (workdays from xx a.m.- xx p.m.) to arrange for a replacement and to obtain their new Accu-Chek Solo diabetes manager including a new pump base and the latest user manual.

As we strive for the highest quality of our products and services at Roche Diabetes Care and are committed to keeping you timely informed on any issue associated with our products we would like to take the opportunity to also notify you today of a voluntary corrective update that we are initiating in relation to our Accu-Chek Solo handling instructions to promote a safe and reliable use of the pump system as intended.

Description of situation and rationale giving rise to this corrective measure

Because patient safety is our top priority, we are informing you today about a potential risk of the reservoir needle being bent or a wet adhesive due to an incorrectly inserted cannula. This can potentially result in insulin occlusion, insulin leakage and an under-delivery of insulin. Such circumstances would be detectable by an occlusion message on the Accu-Chek Solo diabetes manager or recognised by increasing glucose levels, or smelling the leaked insulin. However, this might not always be detected immediately by the user or also go unnoticed by the user e.g. during nighttime. Possible consequences of this issue could range from no clinical impact to adverse health events including hyperglycemia, severe hyperglycemia, or diabetic ketoacidosis (DKA).

Details on affected devices:

Product Description	Reference Number	Device Identifier
● [please insert relevant products from Appendix A]		

Urgent Field Safety Notice

For attention of: **Healthcare Professionals (HCP)**

Manufacturer's reference: SB_RDC_2023_02/03/04

SRN number: DE-MF-000006276

Actions taken by Roche Diabetes Care

We have conducted an in-depth evaluation of the underlying root cause to the above described issue and have updated the handling instructions for the Accu-Chek Solo micropump system. The amended handling instructions for the Accu-Chek Solo system aim to inform and train all users of the system how to correctly place the Accu-Chek Solo micropump on their body to ensure a safe and reliable use of the device as intended.

Recommended Actions:

Please advise your patients using the Accu-Chek Solo system to:

- familiarise themselves with the updated handling instructions as attached to this letter
- always follow these instructions when placing a new infusion assembly on your body or attaching the micropump
- contact our Roche Diabetes Care Customer Care line at xxx-xxx-xxx (workdays from xx a.m.- xx p.m.) in case of any additional questions related to this issue or on how to handle the Accu-Chek Solo micropump system

Communication of this Field Safety Notice

Your national competent authority, distributors, retailers, and users of the Accu-Chek Solo system have been informed about this field action.

We sincerely apologise for any inconvenience this may cause and hope for your understanding and cooperation. Please call our Roche Diabetes Care Customer Care line at xx-xxxxx-xxxxx (workdays from xx a.m.- xx p.m.), if you need any additional advice or have any further questions or concerns. We appreciate your time and attention to this important notification.

Yours sincerely,

Roche Diabetes Care

Appendix A = full list of material, REF and UDI numbers

Appendix B = Updated handling instructions for placing a new infusion assembly and attaching the micropump ([violator](#))